



## Analytical Sample Results

Project Number: 47:1946-F

Abingdon Elementary School

Date: 1/25/2017

Project Address: Arlington, Virginia

Page: 1 of 1

### Air Samples

Sample Location	PCM result	TEM Result
Classroom 161	0.005	<15 s/mm2
Classroom 162	<0.005	<15 s/mm2
Classroom 163	<0.005	<15 s/mm2
Classroom 164	<0.005	<15 s/mm2
Classroom 165	<0.005	<15 s/mm2
Hallway outside Classroom 161	<0.005	<15 s/mm2
Hallway outside Classroom 162	<0.005	<15 s/mm2
Hallway outside Classroom 164	<0.005	<15 s/mm2
Hallway outside Classroom 165	<0.005	<15 s/mm2
Hallway outside Electrical Room 181	<0.005	<15 s/mm2
Library, Reception Desk area	<0.005	<15 s/mm2
Library, Fiction area	<0.005	<15 s/mm2
Library, Non-Fiction area	<0.005	<15 s/mm2
Computer Lab 200	<0.005	<15 s/mm2
Elevated walkway outside Computer Lab	<0.005	<15 s/mm2
North Hallway near Classroom 134	<0.005	<15 s/mm2
Field Blank	NFD	NAD
Field Blank	NFD	NAD

### Bulk Samples of Floor Dust

Sample Location	PLM result
Hallway outside Classroom 161	NAD
Hallway outside Classroom 162/163	NAD
Hallway outside Classroom 164	NAD
Hallway outside Classroom 165	NAD
Hallway outside Storage Room 179	NAD
Hallway/Stairwell outside Electrical Room 181	NAD
Cafeteria Entrance	NAD
Cafeteria, north exit	NAD
Cafeteria Kitchen near Kitchen Office	NAD

Notes:

NAD = No Asbestos Detected

NFD = No Fibers Detected